



# Hotfix Note

in PowerPack for Inventor 2024.1.2



## 1. THREAD MODELER FIX

The Thread Modeler functionality creates a realistic thread using the Inventor thread feature.

The thread can be modeled on the exterior of the element but also as an interior thread for a hole.

In PowerPack for Inventor 2024.1, when the interior thread was created, the functionality was adding material instead of extracting material.

With this hotfix, the thread modeler command from the Powerpack, extracts material also when the thread is an interior one.